

**Cottonwood Creek (HSA 4.51)** at Cottonwood Creek Park upstream (u/s) of Coast Highway (Hwy) crossing (xing). 2005 San Diego Thomas Brothers page 1147. Streamflow ~0.1 cfs. Riparian habitat restoration in progress. Riparian habitat consists of willow, cottonwood, cattails, California evening primrose, watercress...



g. Cottonwood Creek, at Cottonwood Creek Park entrance u/s of Coast Hwy xing. July 12, 2005.



h. Cottonwood Creek, at Cottonwood Creek Park u/s of Coast Hwy xing. Willow riparian habitat. July 12, 2005 0927hrs.



i. Cottonwood Creek, at Cottonwood Creek Park u/s of Coast Hwy xing. July 12, 2005 0927hrs. 2005 Thomas Bros page 1147 C-6.



j. Cottonwood Creek, at Cottonwood Creek Park u/s of Coast Highway crossing and d/s of I-5 culvert. July 12, 2005 0927hrs.



k. Cottonwood Creek u/s of Coast Hwy xing and d/s of the I-5 culvert in background. 2005 Thomas Bros page 1147 C-6.



l. Cottonwood Creek, site 3. N33.05944, W117.28033 Elevation 240ft. Streamflow ~ 1/10 cfs on July 12, 2005 at 1034hrs. Riparian habitat restoration in progress.